






BEST AVAILABLE COPY



























FIG. 11B











FIG. 11C


















14/62


FIG. 11P

















FIG. 14









FIG. 15






















FIG. 21








FIG. 22





- FIG. 23























306

FIG. 31

FIG. 31A




FIG. 31B








FIG. 32














FIG. 35




FIG. 35B




FIG. 35C




FIG. 36






FIG. 37








FIG. 41

FIG. 41A








FIG. 41B



## FIG. 42A












FIG. 45B





FIG. 45C






FIG. 47




FIG. 48A




FIG. 48B




FIG. 48C




FIG. 48D






FIG. 48E








FIG. 50A




FIG. 50B





FIG. 50C



**FIG. 50D** 







FIG. 50E













FIG. 53B


FIG. 53C

FIG. 53A












FIG. 56





FIG. 57







FIG. 58C






FIG. 59E INELASTIC FIBER **STRANDS** 







FIG. 59F






**FIG. 60B** 



**FIG. 60C** 









FIG. 61A






NOTE:OUTER PERIPHERY OF SHOE SOLE EXTENDS SLIGHTLY BEYOND NORMAL EXTREMES OF THE FOOT'S RANGE OF MOTION

FIG. 62













FIG. 65

















FIG. 72G







## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

☐ BLACK BORDERS	
IMAGE CUT OFF AT TOP, BOTTOM OR SIDES	,
☐ FADED TEXT OR DRAWING	
	•
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING	•
☐ SKEWED/SLANTED IMAGES	
a side web/sulattleb images	
COLOR OR BLACK AND WHITE PHOTOGRAPHS	
	•
GRAY SCALE DOCUMENTS	
LINES OR MARKS ON ORIGINAL DOCUMENT	
	•
REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE I	POOR QUALITY
	·
☐ OTHER:	

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.